



Figure 4.1. Bridge for SR 1010 over US 1 in Wake County.



Figure 4.2. Bridge steel superstructure and CIP concrete pier substructure.



Figure 4.3. Patched concrete deck of bridge.